Instruction manual Birth Alarm

How to recognize what model you have:

Mobile 2G (Old Model)
Backside, light sticks out of the housing,
small bulb

Mobile 2.0 The light is flat, integrated into the housing, flat see window





The old 2G model is **NOT** serviceable anymore, for that we have the new substitution program available. If you need more information about the upgrade program, then contact your Birth Alarm dealer for more information.

Birth Alarm Lite/Premium V1(Old) Lights will be on the short side of the BA Lite Birth Alarm Lite 2.0 / Premium Light will be on the long side of the Birth Alarm





The old 2G model is **NOT** serviceable anymore, for that we have the new upgrade program available. If you need more information about the upgrade program, then contact your Birth Alarm dealer for more information.

The newer Birth Alarm Lite 2.0 / Mobile 2.0 and premium are serviceable and can be repaired. Contact your Birth Alarm dealer for more information about repairing your Birth Alarm.